

	<b>PART - GROUP CHANGE NOTIFICATION</b>				<b>Bulletin no</b>	<b>Rev no</b>	<b>Date</b>	
	<b>Prepared by</b>	Ahmet Burak Top Musa Altıparmak			WM_2016_4	0	07.03.2016	
	<b>Approved by</b>	Seyhun BAKIRHAN						
<b>Copy to</b>	TH-YPLB		ÇMİ-MTk1		ÇMİ-ÜPB		ÇMİ-MÜT	
	ÇMİ-KGB		ÇMİ-MTk2		ÇMİ-MTk3		Other .....	

**TECHNICAL EXPLANATION OF THE CHANGE**

<b>Issue</b>	<b>E03 Fault Problem</b>
<b>Explanation</b>	
<p>If you have faced with E03 fault code at machine, the main problem could be occur with Thinking NTC 2804980200 stock number 472 F4E firm code. Because there was very tiny yellow substance on chip caused low resistance values. If you have faced with this kind of problems, please check the NTC resistance value and firm code and change with suitable one. If E03 fault code is detected the program finishes immediately.</p>	
<b>After</b>	<b>Before</b>
	 

**INFORMATION ABOUT THE PART CHANGES**

Ser. Ref	New part(s)				Code	Ser. Ref	Old Part(s)				Code
	Stock number	Part name	Aset				Stock number	Part name	Aset		

**CODE EXPLANATION :**

**A**-Old stocks can be used; Old & new parts are fully interchangeable

**B**-Old stocks can be used; Old parts are interchangeable with old productions & new parts are interchangeable with new productions

**C**-Old stocks can not be used. New parts are interchangeable with old & new productions

**D**-Old stocks can not be used. New parts are interchangeable with new productions

**E**-Old stocks can be used in old productions. New parts are interchangeable with old & new productions

1-Performance / 2-Production improvement / 3-Safety / 4-Material or dimension change / 5-Additional part / 6-Part cancellation / 7-Alternative use

**INFORMATION ABOUT THE PRODUCT CHANGES**

No	Date	Brand	Model	Started from	Finished at	Signature
1						
2						
3						
4						
5						