_			PART - GROUP CHANGE NOTIFICATION							Bulletin	no	Rev no	Da	ite			
● ∂	rçelik		py to	Musa ALTIPARMAK Adem AYHAN						2022_2	0	0	15.0	5.2022			
		Appr	oved by		Yunus Emre Aydoğdu					2022_2							
TECHNICAL EXPLANATION OF THE MODIFICATION													Technical Bulletin No				
s	Subject	Shock absorber change in Large products															
Ke	y Words	Shock a	bsorber v	wiht U-bracke	t												
Proble	Problem description / Reason of the modification:																
	due to the quality problems in the metal bracket shock absorbers of large products, the shock absorber has been replaced. After May 15, 2022, 2860640100 tock shock absorber will be used instead of the 2829010100 stock shock absorber.																
Affected period:												Application Da	te:				
01.05.2022 before												15.05.2022					
Content of the modification (Which items are modified?):																	
Instead	nstead of Aksistem company's U bracket shock absorber, Suspa company's shock absorber has been replaced. There is no difference in mounting structure.																
+																	
Neede	d equipmer the shock at		to be rep	placed, the nu	it used in the shoo	ck abso	rber a	assembly	should be	tightened to	85Nm						
How w	vill be the ap	plication	n of the m	nodification in	n the field?:												
If the sound from the machine continues after the machine foot adjustments are done, the cabinet tox (welding) points should be checked first. As a result of all the checks, if it is confirmed that the sound comes from the shock absorber, the shock absorber must be changed.																	
As a result of all the checks, if it is confirmed that the sound comes from the shock absorber, the shock absorber must be changed.																	
				After								Before					
					INFORMA	TION	ABO	UT THE P	ART CHA	NGES							
Se	er.		New	part(s) / Gro	up(s)		Code	Ser	.		Old	part(s) / Gro	oup(s)		Code		
Re	ef Sto	ock numb	per	Part / gro	oup name	#	Code	Ref	St	ock number		Part / gro	up name	#	Code		
16	46	2860640)100 Sho	ck absorber v	vith bracket	1	E7	164	6 7	2829010100	Shoc	k absorber v	vith bracket	1	E7		
							П								$\overline{}$		
New Pa	urt(s) / Group((e)															
New Part(s) / Group(s) Parts are added to BOM of the product. Parts will not be added to BOM, It is only for service.																	
CODE	EXPLANATIO	ON:															
					y interchangeable												
					eable with old pro changeable with o					changeable w	ith ne	w production	ons				
					changeable with n												
E- Old s	stocks can be	e used in	old produ	uctions. New	parts are intercha	ngeabl	e with	n old & ne									
1-Perfo	rmance / 2- Pi	roduction i	improveme	ent / 3- Safety /	4- Material or dimen	sion ch	ange /	5- Addition	al part / 6-	Part cancellation	n / 7- Al	ternative use					
							ATED	PRODU									
No	Modification	n Date	Br	and	M	lodel			Start	ed from		Finished at	Signature				
\vdash		_									\vdash		$\overline{}$				
.Se	nsitivity:	Public															